

Message

From: Spurlin, Steve [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=7AE2616803EE42B9B9F19A2B12FCE89F-SPURLIN, STEVE]
Sent: 4/16/2019 9:15:16 PM
To: Todd Taylor [todd.taylor@tetrattech.com]
Subject: Fwd: Colonial Tuesday Update 4/16/19

Sent from my iPhone

Begin forwarded message:

From: "Wyatt, John M." <JMWyatt@colpipe.com>
Date: April 16, 2019 at 4:02:00 PM CDT
To: "spurlin.steve@epa.gov" <spurlin.steve@epa.gov>
Cc: "Glaze, Gregory" <GGlaze@colpipe.com>, "Cazares, Juan" <JCazares@colpipe.com>
Subject: Colonial Tuesday Update 4/16/19

Steve,

Today we started the installation of an additional trench up-gradient of interceptor trench 4. When completed, it will be added to an updated map and communicated.

We continue to recover out of the trench along the creek, however, occasional drops of sheen appear in the creek at the southernmost end of the seep. Our OSRO stated that it takes about 45 seconds to remove once it appears.

If you have any questions or I left out any particulars, let me know and I will ensure they are added to future emails.

Thanks,

John M. Wyatt
Environmental Program Manager
Southeast District

Colonial Pipeline Company
4295 Cromwell Rd. #311
Chattanooga, TN 37421
Ph: 423-713-7568
Fax: 770-754-8119

Colonial Pipeline Notice - This e-mail message (including any attachment) contains information that may be confidential, be protected by attorney-client or other privilege, or constitute non-public information. If you are not the intended recipient, please notify the sender by electronic mail or telephone and delete the original message without making any copies. Use, dissemination, distribution, or reproduction of this message by unintended recipients is not authorized and may be unlawful.